

**ENGINEERING CHANGE NOTICE**  
**DART AEROSPACE LTD**

MPP

Date: 11.08.24	Job No.:	ADR Yes/No: NO	ADR Date:	ECN #: 11- 627
Product No.: D412-791		Created By: KB	Approved By: <del>KB</del>	
Product Name: Safety Enhancement Kits		Checked By: <del>KB</del>	General Manager Approval: N/A	

Distribution	Reqd	Resp	Initial / Date
Production Manager / Coord.	Y	LL	
Purchasing Coord.	N		
Production Engineering Coord.	Y	EC/DO	

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord.	N		
QC Coordinator	N		
Customer Technical Support	Y	MB	
Marketing	Y	SW	
Customer Order Processing	N		

**Reason for Change:**

To correct a problem with Bell 212 wiring and to correct a possible problem with powering the MCP when CB is pulled on D412-791-047 kit.

**Documents Affected:**

DR-D412-791 Rev. C  
MDL-D412-791 Rev. D  
IIN-D412-791 Rev. C  
ICA-D412-791 Rev. 1  
D412-791-907 Rev. D

**PARTS MUST COMPLY**

**PREVIOUS PARTS SATISFACTORY**

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	Y	SW	Send a copy of IIN, ICA and D412-791-907 to Alpine	
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Master Document List (MDL)	Y	KB	MDL-D412-791 Rev. D	<i>for KB 11.09.07</i>
6	Update Product Compatability Matrix	N			
7	Create Eurocopter Form (FEE)	N			
8	Notify TC / FAA of Change	N			
9					

#	Document Control Actions	Reqd	Resp	Notes	Complete
10	Move Electronic Files/Design Journal	Y	KJ		<i>11.09.07</i>
11	Update Product Specification Files	Y	KJ		<i>11.09.07</i>
12	Update Approved/Preliminary Dwg PDF Files	Y	KJ		<i>11.09.07</i>
13	Update Document Record (DR)	Y	KB	DR-D412-791 Rev. C	<i>for KB 11.09.07</i>
14	Update Product Development Summary	N			
15	Update QSI 021 and/or STC Approval List	N			
16	Update Parts / STC Database	N			
17	Update / Verify ARC Database	N			
18	Create / Update Change Record Form / Item Card Database	Y	KJ	D412-791-047 now at Change 002	<i>11.09.07</i>
19	Create / Update PPP's	Y	KJ		<i>11.09.07</i>
20	Red Decals required?	N			
21	Update Document Control Database / Laminated Dwgs	N			
22	Update Grey Project / Electronic Binder PDF Files	Y	KJ	Files uploaded to Kim Folder	<i>11.09.07</i>
23	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		<i>11.09.07</i>
24					

**Description / Action:**

- IIN-D412-791, ICA-D412-791 and D412-791-907 to be released to correct a wiring problem with Bell 212 and to prevent the possibility of the Pitot Heat powering the Master Caution Panel.

*2st*

- Update D412-791-047 kits in stock to add new paperwork and add 2x 1n4007 diodes.

*W/O P3639*

- Update BOM for D412-791-047 to change quantity of 1N4007 from 4 to 6.

ECN Verified & Complete: \_\_\_\_\_

Date: \_\_\_\_\_